

Certificate

Admission to implementation
of Volkswagen test regulations



by

Volkswagen AG
Materials technology

for

BOSMAL Automotive Research and Development Institute Ltd
Ul. Sarni Stok 93
43-300 Bielsko-Biala
Poland

The laboratory service provider **BOSMAL Automotive Research and Development Institute Ltd** has successfully compared the test procedures listed in the Appendix at the above-mentioned locations or at the aforementioned sub-suppliers with Volkswagen.

This certificate entitles the laboratory service provider to offer the tests listed in the Appendix worldwide as a certified laboratory service provider of Volkswagen **from 01.01.2025 to 31.12.2026**, in accordance with the regulations in the declaration of conformity issued by him.

Wolfsburg, den 20.01.2025

List of test procedures that can be offered to Volkswagen suppliers

Blatt 1 von 1

Service provider: **BOSMAL Automotive Research and Development Institute Ltd**
Region: **Europa**

Location or subcontracting in the attached location legend



Zertifiziert von
Volkswagen

Label	Description of test procedures	Note	Location
1 TL 1058	Chrome-Plated Surfaces; Determination of the Micro-Crack Pattern on Chrome-Plated Surfaces		A
2 PV 1303	Non-Metallic Materials; Xenon Arc Light Aging of Vehicle Interior Components		A
3 PV 3330	Elastomer O-Ring Seals; Compression Set (Permanent Deformation)		A
4 PV 3955	Trim Cover Material; Determining the Seam Slippage Resistance of Trim Cover Material - Woven Fabrics		A
5 PV 3964	Surfaces in the Passenger Compartment; Testing of Cream Resistance		A
6 PV 3991	Structured surfaces, skin abrasion testing		A
7 VW 50195	Colorimetric Evaluation of Exterior Automotive Paint Finishes		A

Location legend:

Service provider: **BOSMAL Automotive Research and Development Institute Ltd**
Region: **Europa**

Nr.	Company name	Street	Place	Country
A	BOSMAL Automotive Research and Development Institute Ltd	Ul. Sarni Stok 93	43-300 Bielsko-Biala	Poland